Application/Control Number: 10/599,891 Page 2

Art Unit: 3754

REASONS FOR ALLOWANCE

1. The following is an examiner's statement of reasons for allowance: the primary reason for allowance is the inclusion of the limitation "wherein the said pivotal interconnecting element has one end which is pivoted directly onto a movable control member of the second dispenser device" in combination with the other claimed elements.

Any comments considered necessary by applicant must be submitted no later than the payment of the issue fee and, to avoid processing delays, should preferably accompany the issue fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for Allowance."

Conclusion

Any inquiry concerning this communication or earlier communications from the examiner should be directed to JONATHAN WOOD whose telephone number is (571)270-7422. The examiner can normally be reached on Monday through Friday, 7:30 AM to 5 PM.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Kevin Shaver can be reached on (571)272-4720. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Application/Control Number: 10/599,891 Page 3

Art Unit: 3754

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/JKW/ Examiner, Art Unit 3754

/Kevin P. Shaver/ Supervisory Patent Examiner, Art Unit 3754